

Außen-Gewindedrehen / External threading

SXAN 90°  08 ER/L.. 11 ER/L.. 16 ER/L.. 22 ER/L.. <i>Seite / Page G.03</i>	STAN 90°  16 ER/L.. 22 ER/L.. 27 ER/L.. <i>Seite / Page G.03</i>	CTAN 90°  16 ER/L.. 22 ER/L.. 27 ER/L.. <i>Seite / Page G.04</i>	SXGN 90°  <i>Seite / Page G.04</i> R/L 166G-3.. R/L 166G-4..	STXN 90°  16 ER/L.. 22 ER/L.. 27 ER/L.. <i>Seite / Page G.05</i>	CTXN 90°  16 ER/L.. 22 ER/L.. 27 ER/L.. <i>Seite / Page G.05</i>
STCN 90°  TNMC 1603.. TNMC 1603.. TNMC 2204.. TNMC 2204.. <i>Seite / Page G.06</i>	CXAP 90°  R/L 166-3.. R/L 166-4.. <i>Seite / Page G.07</i>				

Innen-Gewindedrehen / Internal threading

SXFN 90°   <i>Seite / Page G.08-09</i> 11 NR/L.. 22 NR/L.. 27 NR/L..	STXN 90°  16 NR/L.. 22 NR/L.. 27 NR/L.. <i>Seite / Page G.09</i>	CTXN 90°  16 NR/L.. 22 NR/L.. 27 NR/L.. <i>Seite / Page G.10</i>	STGN 90°  <i>Seite / Page G.11</i> TNMC 1603.. TNMC 2204..	STGP 90°  <i>Seite / Page G.11</i> TPMC 1603.. TPMC 2204..	CXFP 90°  <i>Seite / Page G.12</i> R/L 166-2.. R/L 166-3.. R/L 166-4..
---	--	--	--	--	---